

#### DESCRIPTION

UltraMean is a superior, highly concentrated cleaner and brightener in one. It removes dirt and stains caused by mildew and tannins. For use on exterior surfaces and decks, to clean and brighten weather-beaten wood. Safe for use on Trex® and other plastic/wood composite surfaces. Neutralizes stripped surfaces while removing mill glaze.

#### FEATURES

- Contains no harmful bleach (sodium hypochlorite), T.S.P. (caustics) or sodium hydroxide
- Cleans and brightens
- Fast acting and easy to use

#### SUGGESTED APPLICATIONS

- Remove mildew and clear finishes to restore wood to its original look.
- Remove mill glaze, usually found on new wood, which should be removed prior to applying a finish.
- Neutralize and brighten surfaces that have been stripped with corrosive strippers.
- Remove tannin stains from bleeding wood, such as cedar and redwood.
- Ideal for cleaning and brightening most exterior surfaces, especially outdoor wood furniture, fences, decks, and docks, including Trex and all other plastic/wood composite decking materials.
- Use on all wood products, vinyl siding, drywall, decking, studs, basement walls, shake shingles, concrete walkways, joists, fencing, patios, fiberglass, tile, fiberglass shingles, painted concrete, brick, crating, cordage and natural fibers, flooring and patio furniture (wood and plastic). DO NOT USE ON ALUMINUM or other METALS.

#### REGULATORY DATA

- Considered Non-Hazardous by the D.O.T.
- Does not Contain any VOC'S.
- Severe eye irritant, vapor is harmful, solution harmful if swallowed

**DO NOT ALLOW TO FREEZE**  
**KEEP OUT OF REACH OF CHILDREN**

#### SURFACE PREPARATION

PLEASE NOTE: Even though UltraMean is a naturally occurring and biodegradable acid, it is still strong and may harm plants until sufficiently diluted. Pre-wet grass and plants before covering with plastic around the area where cleaning is being performed. When done uncover and rinse with water thoroughly.

Surface should be dry and free of debris before applying UltraMean. Protect any surface that will not be cleaned, especially aluminum. UltraMean will etch and discolor aluminum. Protect all surfaces from rinse water.

#### MATERIAL PREPARATION

- Shake well or mechanically blend.
- Use only clean water to dilute.
- Mix concentrate with four parts water.
- Do not mix with any other products.
- Always wear personal protective equipment when handling this or any other chemical. See safety cautions.

#### COVERAGE

Up to 2,500 square feet per gallon with a five to one water dilution. Coverage varies depending on surface texture and absorption ability. Overspray and waste in tools will affect coverage.

#### STORAGE

- Thoroughly wash down all equipment after use.
- Store in a cool, dry place.
- Do not transfer contents to unlabeled bottles or other containers.
- Keep away from heat, sparks, or open flame. Contact with open flame or hot surface may produce toxic gases.

#### SURFACE TESTING

- Always performs a test in an inconspicuous area to determine whether desired results will be achieved.
- The test area should be cleaned to determine precise procedures necessary for most effective cleaning.
- User shall determine the suitability of the product for its intended use and assume all risks and liability whatsoever in connection therewith.

# UltraMean Exterior Mold Stain Remover

## APPLICATION GUIDELINES

- Read and understand all directions and safety information before use.
- Use caution when opening, with container away from face.
- Close after each use.
- Use in well ventilated areas only.
- UltraMean may make surfaces slippery. Use extreme caution.
- Use OSHA approved safety belts and non-slip steel pegged roof shoes when necessary for roof-tops.
- Do not mix with other products, especially those containing chlorine or bleach.
- Dilution is recommended one (1) part UltraMean to four (4) parts water. Extremely dirty or weathered surfaces may require a second application. For surfaces that are lightly stained, it may be possible to dilute UltraMean with more water.
- For best results, use when outdoor temperatures are between 45°F and 80°F.
- Apply a liberal coat to surface in a uniform direction, using a brush, mop or pump sprayer with no aluminum parts.
- For fence or siding, use a deep nap or sponge roller, working from bottom up. Apply in 10 board increments to maintain wetness.
- Allow 10-20 minutes dwell time, keeping surfaces wet.
- If using a hose, scrub the solution using a stiff, short bristle brush, then hose down with water.
- If using a pressure washer, scrubbing may not be necessary. Set pressure washer to 2,500 max psi to clean surface. For wood, do not use more than 1,000 psi. Pressure washer not recommended for composite.
- When rinsing vertical surfaces, continually rinse the cleaned surface to avoid streaking.
- Always wash in the direction of the wood grain.

## SAFETY CAUTIONS

- Contains oxalic acid (146-62-7).
- Causes severe dermatitis and burns.
- Avoid contact with eyes and prolonged contact with skin.
- May be irritating to eyes, nose and throat, causing eye and skin irritation.
- Avoid breathing fumes. If spraying, use NIOSH approved respirator.
- Intended for EXTERIOR use, use ONLY in well ventilated areas.
- Use chemical resistant (polyethylene) gloves to protect hands, use safety glasses to protect eyes.
- Wash thoroughly after use.
- Review SDS before using.

After cleaning surfaces with UltraMean or UltraMean2, reduce further maintenance costs and effort by applying UltraBan® The Invisible Shield® to PRESERVE, PROTECT and PREVENT against the destructive effects of mold and mildew within its dried film.

## CLEAN UP

- Rinse thoroughly with water. Water flush shrubbery, sidewalks, blacktop, asphalt, equipment and all adjacent surfaces immediately upon contact.

## DISPOSAL

Dispose of in accordance with federal, state, and local regulations. Puncture container after rinsing to prevent re-use.

UltraMean is biodegradable and non-flammable.

## FIRST AID

Eyes: Rinse eyes thoroughly for 20 minutes while lifting eyelids to ensure thorough cleaning. Get medical attention immediately.

Skin: Remove contaminated clothing immediately. Rinse skin thoroughly for 20 minutes. Wash and clean contaminated clothing and shoes before reusing.

Inhalation: Get fresh air immediately. If unable to breath, administer artificial breathing and get immediate medical attention.

Ingestion: Do not induce vomiting. If conscious, give large amounts of water. Call a physician, poison control center or emergency room.

## LIMITED REMEDY

Follow the instructions carefully. If your application is not covered by these instructions, call 863-665-0203 before using this product. Buyer agrees that if HomeWood Solutions' products are proved defective, the user's exclusive remedy will be, at HomeWood Solutions election, to replace the defective product or refund the purchase price for the defective quantity.